














EXHIBIT B





ALTERNATE NUMBER	DESCRIPTION	IMAGE
1	SIDEWALK REPAIR LOT D PREFERRED	
2	SIDEWALK REPAIR AT CU ENTRY 1	
3	SIDEWALK REPAIR LOT C TO AH ENTRY 2	
4	CONCRETE REPAIR LIBRARY PLAZA	





ALTERNATE NUMBER	DESCRIPTION	IMAGE
5	SIDEWALK REPAIR NEAR LIBRARY ENTRY 2	 A photograph showing a concrete sidewalk repair area. The repair is a rectangular patch of lighter-colored concrete. In the background, there is a large, modern building with a glass facade, identified as the library. A blue handicapped parking sign is visible on the left side of the sidewalk.
6	SIDEWALK REPAIR SEM ENTRY 1	 A photograph showing a sidewalk repair area. The repair is a rectangular patch of lighter-colored concrete. In the background, there is a building with a glass facade. A black trash can is visible in the foreground on the right side of the sidewalk.
7	SIDEWALK REPAIR SEM ENTRY 7	 A photograph showing a sidewalk repair area. The repair is a rectangular patch of lighter-colored concrete. An orange traffic cone is visible in the foreground on the right side of the sidewalk.
8	CURBING REPAIR SEM ENTRY 5	 A photograph showing a curbing repair area. The repair is a rectangular patch of lighter-colored concrete. A red metal railing is visible in the foreground on the left side of the sidewalk.

ALTERNATE NUMBER	DESCRIPTION	IMAGE
9	SIDEWALK REPAIR MB ENTRY 3	 A photograph showing a concrete sidewalk repair. The repair area is a rectangular patch of concrete, bordered by a decorative border of light-colored, rounded stones. The surrounding sidewalk is made of larger concrete slabs.
10	SIDEWALK REPAIR MB ENTRY 3	 A photograph showing a concrete sidewalk repair. The repair area is a rectangular patch of concrete, bordered by a metal grate. The surrounding sidewalk is made of larger concrete slabs.
11	SIDEWALK REPAIR MB ENTRY 3	 A photograph showing a concrete sidewalk repair. The repair area is a rectangular patch of concrete, bordered by a metal grate. The surrounding sidewalk is made of larger concrete slabs.
12	SIDEWALK REPAIR MB ENTRY 3	 A photograph showing a concrete sidewalk repair. The repair area is a rectangular patch of concrete, bordered by a metal grate. The surrounding sidewalk is made of larger concrete slabs.

ALTERNATE NUMBER	DESCRIPTION	IMAGE
13	SIDEWALK REPAIR LOT G TO MB 3 CROSSWALK	 A photograph showing a concrete sidewalk with a significant crack. A red-painted curb runs along the edge of the sidewalk, and a white crosswalk is visible on the asphalt road surface to the right.
14	STEPS REPLACEMENT SEM ENTRY 5	 A photograph of a set of concrete stairs with a red metal railing. The stairs appear to be in good condition but are the subject of a replacement project.
15	SIDEWALK REPAIR FM SHIPPING DOCK	 A photograph of a concrete sidewalk area featuring a square storm drain. There are several cracks in the concrete, particularly around the drain and extending towards the left.
16	DRIVE REPAIR SHIPPING RAMP	 A close-up photograph of a concrete ramp or driveway surface. A prominent, irregular crack runs across the width of the ramp.

ALTERNATE NUMBER	DESCRIPTION	IMAGE
17	SIDEWALK REPAIR WC ENTRY 2	
18	SIDEWALK REPAIR LOOP ROAD BY POND OVERFLOW	
19	ASPHALT DRIVE REPAIR CPD	
20	ASPHALT DRIVE REPAIR CPD	

ALTERNATE NUMBER	DESCRIPTION	IMAGE
21	ASPHALT REPAIR PARKING LOT A SOUTH	 A close-up photograph showing a section of asphalt pavement adjacent to a concrete curb. The asphalt surface is dark grey and appears to be a repair area, with some loose material and a crack visible along the edge of the curb. The curb is light-colored concrete.
22	ASPHALT REPAIR PARKING LOT A	 A photograph of a wide asphalt surface in a parking lot. The asphalt is light grey and shows several prominent, dark, irregular cracks that run across the surface. The cracks are most visible in the center and right side of the frame.
23	ASPHALT REPAIR PARKING LOT A	 A photograph of an asphalt surface in a parking lot, similar to the previous image. It shows a network of dark, irregular cracks on a light grey asphalt surface. A concrete curb is visible in the upper left corner of the frame.
24	ASPHALT REPAIR PARKING LOT A	 A photograph of an asphalt surface in a parking lot, showing a similar pattern of dark, irregular cracks on a light grey asphalt surface. A concrete curb is visible in the upper left corner of the frame.

ALTERNATE NUMBER	DESCRIPTION	IMAGE
25	ASPHALT REPAIR PARKING LOT A	
26	ASPHALT REPAIR PARKING LOT A	
27	ASPHALT REPAIR REGENTS LOOP BY MB ENTRY 2	
28	CONCRETE REPAIR BY CU 1 (2 SPOTS MIRRORED ON SIDEWALK)	

ALTERNATE NUMBER	DESCRIPTION	IMAGE
29	CONCRETE REPAIR STEPS AT MB ENTRY 1	